



**Hubshell**

100

110

**A** NDS Flange  $\varnothing$

47mm

47mm

**B** NDS Center to Flange

24mm

29mm

**C** DS Center to Flange

37mm

42mm

**D** DS Flange  $\varnothing$

42mm

42mm

\*For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing\*