



**Hubshell**

142

148

**A** NDS Flange  $\varnothing$

47mm

47mm

**B** NDS Center to Flange

35mm

38mm

**C** DS Center to Flange

20mm

23mm

**D** DS Flange  $\varnothing$

60mm

60mm

\*For Flange to Dropout Value Subtract Center to Flange Value from 1/2 of Dropout Spacing\*